



1



2x - 1x1 Connector Pins





1x - 1x12 Beam



2



1x - 1x12 Beam




3



3x - 1x1 Connector Pins





1x - 1x12 Beam



4





1x - Step 2 Assembly



5



1x - 1x12 Beam





6



2x - 1x1 Connector Pins





1x - 1x8 Beam



7



1x - Step 5 Assembly







8



1x - 1x8 Beam





9



2x - 1x1 Connector Pins



1x - 1x6 Beam





10



2x - 1x1 Connector Pins



1x - 1x6 Beam







2x - 1x1 Connector Pins




1x - 3x4 Tee Beam



12




1x - 2x Wide, 2x2 Corner Connector





13



2x - 1x1 Connector Pins



1x - 3x4 Tee Beam



14



1x - 2x Wide, 1x2 Offset Corner Connector

